

Underpinning and Seismic Upgrade


Salt Lake City Capital Building

Marc Mastrantuono, P.E. Geotechnical Division Manager Ischebeck USA, Inc.


ISM Workshop 06/2023


Geology – Wasatch Fault

- Located at the Western base of the Wasatch range
- Area has the greatest earthquake risk in the interior western US
- Made up of 10 segments, Avg 25 miles (40km) in length each
 - 5 central segments offer the highest risk
- Each segment has the ability to rupture independently
- Effects 1.6 million people
 - 80% of Utah residents live along the fault




Geology – Wasatch Fault





Geology – Wasatch Fault

- Most recent earthquake March 2020
- 5.7 magnitude
- 2,590 aftershocks throughout the following year.
- Over the last 10,000 years a large event has taken place every 900-1300 years.
- It's been 1200-1600 years since a 7.0 or greater event has happened along the Salt Lake City Segment.
- "Overdue for large earthquake"




- Built in the early 1900s
- 4 stories with crawl space
- Constructed using reinforced concrete frame
- Later analysis indicated the building would perform poorly during a seismic event
- The concept of seismic design did not exist 100 years ago
- \$200 million seismic upgrade from 2004 to 2008




Shear Walls

New shear walls



Challenges


- Plan required complete removal of existing foundation system
 - Other solutions would have caused damage to the original historical structure. Higher overall cost.
- Very heavy structure. Roughly 2x the weight of modern office building of comparable size
 - Dome amplifies seismic forces due to weight
- Structure built on slope
 - West side of building had limited access
 - Required breaking out portions of floor above
- During construction, the structure could not sustain more than 1/16[°] of movement




Base Isolator


265 base isolators to be installed


- Base Isolation is one of the most popular and effective tools against earthquake forces
- Decouples structure from the structure base (foundation)
- Vertically stiff
- Horizontally flexible







Base Isolator










- Columns 14ft O.C.
- "Thousands of Micropiles"
- Over 3000 micropiles
- Pile groups of TITAN T30/11 and TITAN T40/16
- Column loads Ranged from 200kips – 900+ kips



- Isolator
- Pile Cap










East Side of building














- 30" temporary load transfer slab
- ~ 5ft wide















- In areas where columns were not symmetrical, steel beams were used to transfer the load
- Approximately 40 columns removed at a time



- Jacks to apply pressure just until there was a load transfer
- Not wanting to lift




- During construction, the structure could not sustain more than 1/16" or movement
- Actual movement up to 1/1000th inch















- Each rotunda pier carried close to 10,000kips
- Micropiles used for soil retainage to create pit for new pile cap
- Soil underneath new rotunda pile caps required 20kips per sqft of bearing capacity
- Micropiles used solely for ground improvement


















Summary




- During an earthquake, the structure will be able to move 2 feet in each direction for a total "swing" of 4 feet
- Horizontal seismic forces reduced by approximately 75% to 80%
- Structure will be able to withstand a 7.2 magnitude earthquake with minimal damage
- Large earthquake previously would have likely result in loss of the structure and loss of life

Summary

Why Micropiles

Limited access

- Low vibration
- Tried jet grouting but deemed too messy under the building
- Spoils and grout easier to control with hollow bar
- Other methods to retrofit the building would have disturbed historical characteristics of the building
- Not enough space to use traditional spread footings for required soil bearing pressure





Thank you for your attention

Marc Mastrantuono, P.E. Geotechnical Division Manager Ph: 239.316.2049 E: marc@ischebeckusa.com www.lschebeckUSA.com

*Photos and supporting information courtesy of Reaveley Engineers