

HIGH CAPACITY MICROPILES WITH UNIQUE TESTING REQUIREMENTS FOR PARKING STRUCTURE UPGRADE IN LOS ANGELES

Presented by Pete Speier, P.E.


Williams Form Engineering Corp

6/1/2023



685 CATALINA AVE


- Existing 3-Story Parking Garage in Downtown LA
- To be incorporated into the 3500 Wilshire Development Project
- Foundation Upgrade to allow addition of 4 stories of apartments above the Existing Parking Structure



LOS ANGELES DEPT OF BLDG. & SAFETY



Office of Statewide Health Planning and Development






685 CATALINA AVE

PRE-PRODUCTION TESTING REQUIREMENTS

- 3 Verification Tests to 2*DL (584k)
 - 1 Instrumented Compression w
 TIP
 - 1 Compression
 - 1 Tension (184k)
 - Sacrificial
- Complete Exhumation of Verification Test Pile

• Prepare Report for Submittal as Basis for Production Pile Design



TEST PILES


5 Piles Drilled in Line 9-5/8" Casing in top 17.5' (Unbonded) 8" Diameter Below Casing Total Depth = 70' 2-1/4" 150 ksi Center Bar Reinforcement














C-1











2 TYPES OF PILES

<u>Type 1</u>

138k DL - Compression Only

30' Bond Length (min)

#11 Gr75 Center Bar Reinforcement

Type 2


292k DL - Compression

92k DL - Tension

40' Bond Length

2-1/4" 150 ksi Center Bar Reinforcement

All Piles Used 9-5/8" Casing in Upper 10.5' Center Bar Reinforcement Encapsulated in Bond Length




685 CATALINA AVE

PRODUCTION MP TESTING REQUIREMENTS

- 5% Piles Proof Tested to 1.6*DL
- 10% Piles TIP Tested






























QUESTIONS??

